

2000A AC/DC Clamp-on Adaptor



AC/DC Current measurements to 2000A

Using virtually any MultiMeter with standard banana plug sockets

Features:

- 3.3" (83mm) clamp jaw
- Measures AC/DC Current in two ranges: 0 to 200A and 0 to 2000A and converts it to 1mV/count for reading current on any multimeter or voltage recorder
- Banana plugs connect into standard multimeter sockets and switch multimeter to a millivolt or voltage range
- DC zero adjust; Outputs 1mV/A
- 2% basic accuracy
- Dims: 8.3 x 2.5 x 1.3" (210 x 64 x 33mm)
Weight: 0.91lb (414g)
- Complete with 9V battery, 1.8ft (570mm) cable with banana plugs; one year warranty



Banana plugs connect into standard multimeter sockets



Ordering Information:

- 3809052000A AC/DC Clamp-on Adaptor
380905-NIST.....2000A AC/DC Clamp-on Adaptor with NIST Certificate

